

Gas and Coal Outburst Committee Half Day Seminar Wednesday 19th June 2013

Questioning the Fundamentals and Understanding of What is an Outburst David Gordon – Inspector of Coal Mines



DAVID GORDON

INSPECTOR OF COAL MINES NSW – 2 years

INDUSTRY EXPERIENCE GENERALLY UNDERGROUND

20 YEARS QUEENSLAND 17 YEARS NSW

ROLES
MINER
DEPUTY
UNDERMANAGER
PRODUCTION MANAGER /
UNDERMANAGER IN CHARGE
MINE MANAGER
VENTILATION OFFICER
GEOTECHNICAL ENGINEER



My Questions:

- 1. Does MDG 1004 Outburst Mining Guideline require review?
- 2. What is the lower determination of an outburst event?
- 3. What is the upper limit conditions that would prevent any mining at all?



- CMRA 1982 Section 63 Notice issued 11/5/1994.
- 19 years
- No fatalities related to outbursts
- Substantial amount of research
- Substantial amount of experience
- Since then there have been 30 recorded events



Date	Gas	Structure	Mining Type
		1	
3/03/1995			c/m
1996			
7/09/1996			
1997			
			1
3/04/1998		undrained	Longwall
9/12/2000		Boggy	Remote c/m
19/03/2002		Dyke	c/m
27/05/2009		Boggy	Remote c/m
6/07/2009		Boggy	Remote c/m
7/07/2009	CH4	Boggy	Remote c/m
15/10/2010	CH4	Boggy	Remote c/m
15/10/2010		Boggy	Remote c/m
31/08/2011		Dyke	Shotfiring
2/04/2012		Dyke	Shotfiring
4/05/2012		Dyke	Shotfiring
5/06/2012		Dyke	Shotfiring
5/06/2012		Dyke	Shotfiring
15/06/2012		Dyke	Shotfiring
23/06/2012		Dyke	Shotfiring
12/07/2012		Dyke	Shotfiring
8/08/2012	CH4	Dyke	Shotfiring
25/08/2012	CH4	Dyke	Shotfiring
17/10/2012	CO2	Fault Zone	c/m
20/12/2012	CH4	Dyke	Shotfiring
9/01/2013		Dyke	Shotfiring
18/01/2013	CH4	Dyke	Shotfiring
19/01/2013	CH4	Dyke	Shotfiring
11/03/2013		Dyke	Shotfiring
		-	
9/05/2013	CH4	Dyke	Shotfiring
19/05/2013		Dyke	Shotfiring

- Data to my knowledge to date
- Information is welcome to clarify blanks in late 90's
- 30 incidents
- 23 in remote mining circumstances
 - 17 shot firing induced in proximity to structure
 - 6 remote c/miner
- 2 mining with c/miner with men at the face
- 2 on longwall face with men on the face
- 3 require information





Department of Mineral Resources New South Wales



Outburst Mining Guideline

MDG No: 1004

July, 1995

- MDG No: 1004
- Date of Issue: 26 July 1995
- Refers to all mines
- Refers to old legislation
- No reference to Longwall
- Appendix 2 contains an outburst report form – I have not seen this used
- Review of this document?





Department of Mineral Resources New South Wales



Outburst Mining Guideline

MDG No: 1004

July, 1995

- MDG No: 1004
- Definition
 - "Outburst the sudden release of gas and material from the working place that can vary in magnitude and intensity"
- RD Lama referred in his work
 small outbursts are of less
 than 2 tonnes
- Are "slumps" of material that coincide with a measurable release of gas classed as an outburst?



- Outburst Threshold Limits dictate the style of mining that will be conducted.
- Below a set gas content normal mining will be conducted
- Above a set gas content a remote style of mining will be conducted
- Is there an upper limit where no mining will take place?



My Questions:

- 1. Does MDG 1004 Outburst Mining Guideline require review?
- 2. What is the lower determination of an outburst event?
- 3. What is the upper limit conditions that would prevent any mining at all?

david.gordon@industry.nsw.gov.au

